PAPER • OPEN ACCESS

Analysis of SOS Results for Engine Lubricants Contaminated by the Fuel in The 3516 TA Diesel Engine Generator Set

To cite this article: Wilarso et al 2021 J. Phys.: Conf. Ser. 1764 012172

View the article online for updates and enhancements.

You may also like

- The Effect of Dual-injector on Combustion Process of 396 Series Diesel Engine with Shallow Basin-shaped Combustion Chamber

Yu Liang, Liying Zhou and Haomin Huang

- <u>Engine Modelling of a Single Cylinder</u>

<u>Diesel Engine Fuelled by Diesel-Methanol</u>

Blend

Erdiwansyah, A.M. Leman, Fitri Khoerunnisa et al.

 Performance and emission study of exhaust gas single cylinder diesel engine based on fuel bioethanol – high speed diesel (HSD) using fumigation and blending methods

I Rosyadi, Haryadi and Henry



1764 (2021) 012172 doi:10.1088/1742-6596/1764/1/012172

Analysis of SOS Results for Engine Lubricants Contaminated by the Fuel in The 3516 TA Diesel Engine Generator Set

Wilarso^{1*}, Aswin Domodite¹, Hilman Sholih¹ and Mujiarto²

¹Department of Mechanical Engineering, Sekolah Tinggi Teknologi Muhammadiyah Cileungsi, Cileungsi, Bogor, Indonesia 16820

²Department of Mechanical Engineering, Universitas Muhammadiyah Tasikmalaya, Tasikmalaya, Indonesia

Abstract. Generator Set Unit that operates in the PLTD, during operation there is a knocking sound at cylinder position # 14, after checking and removing the injector there is diesel in the combustion chamber and indicated glowing in the exhaust manifold. The purpose of this study is to determine the root causes of knocking and diesel fuel in the combustion chamber. This research method uses oil sample testing to be tested in the laboratory. The results of the analysis of oil contaminated with diesel fuel are caused by diesel oil flowing into the pan oil and after checking the cylinder head crack (groove-shaped) is found on the side of the injector seal holder, when the unit is not operating the diesel flows into the combustion chamber and into the oil reservoir. The groove in the cylinder head is formed, caused by a hard injector seal caused by fuel temperature and high water temperature. The solution of this research is that the pressure on the fuel return from the engine should not exceed 27 kPa, while the maximum fuel temperature is 66 °C (150 °F), and what needs to be done is an improvement of diesel cooling and routine radiator maintenance.

1. Introduction.

Generator Set which operates in one of the PLTD does not operate, due to experiencing engine oil mixed with diesel and indicated knocking when the unit is operating. The knocking indication occurs because the ratio of air to fuel is unbalanced, if left too long to operate will cause damage to the exhaust valve and intake valve [1]. After checking the engine, diesel fuel is found to flow from the inside of the cylinder liner and there is diesel fuel in the combustion chamber [2]. When the lubricating oil is mixed with the fuel, the viscosity (the ability of the oil to hold the flow rate decreases) will reduce the lubricating oil, this condition will damage the oil function which will cause damage to the engine components. The unit for reading viscosity in cSt (centistoke). Lubricant contaminating fuels also reduce the concentration of additives present in oil [3]. Excessive fuel contamination in oil can reduce the nature of the lubricating oil which will result in engine damage. Lubricating oil contaminated with diesel fuel will affect the decrease in oil pressure (low oil pressure) and increase the oil level. Fuel dilution decreases the ability of the oil film to protect moving parts [4]. Also, due to the reduced concentration of additives, lubricating oils do not have adequate amounts of anti-wear additives and corrosion inhibitors [5].

Published under licence by IOP Publishing Ltd

^{*}wilarso@sttmcileungsi.ac.id

Content from this work may be used under the terms of the Creative Commons Attribution 3.0 licence. Any further distribution of this work must maintain attribution to the author(s) and the title of the work, journal citation and DOI.

1764 (2021) 012172 doi:10.1088/1742-6596/1764/1/012172

To meet stringent standards, the Common Rail fuel injection system has been implemented, which increases fuel injection pressure and introduces multi-stage dosing. The cost of repairs is very high because of sophisticated parts and technology and to reduce the cost of repairs [6]. In figure 1, the damage to the injector is explained [7].

In the explanation in Figure 1, 1) Daily tank functions to collect fuel after leaving the engine, 2) the strainer functions to filter large particles before entering the fuel system. 3) Primary filter functions to filter small particles in micron size, 4) Fuel transfer pump to transfer to the fuel system, 5) Secondary filter functions to filter particles under 5 microns, 6) tube (supply) to deliver fuel to the injector, 7) The injector functions to inject fuel into the fuel chamber, 8) Tube (return) distributes the material after the injector, 9) The fuel cooler functions to cool the fuel after the injection system, the damage that occurs at no. 7 (injector).




Figure 1. Position of damage to the injector

2. Literature Review.

Cracks in the injector seal holder causes fuel to flow into the combustion chamber [2]. n table 1 the standard readout of the oil test results is based on reference from manufacturing. Where diesel fuel is still recommended in tests below <4%. And if the value is above >4%, then it is immediately conditioned to the relevant parties regarding this matter [8]

Viscosity, hotspot and flashpoints are chosen as the most important parameters to follow changes in the fuel-oil mixture. Lubricant is diluted based on the results of the maximum oil laboratory analysis recommended units to be stopped or by testing engine oil that is contaminated with diesel fuel [4], so as not to cause great damage.

3. Statement of Problem.

Diesel engine oil contaminated from the results of SOS testing (schedule oil sampling) and visual checking in the field.

4. The Objective of Work.

- Check the cylinder head holder.
- Link damage to the injector holder with oil sampling testing.

5. Problem Description.

Knocking sound when the diesel engine is operating, after checking there is a fluid leak from the inside of the cylinder liner. Diesel fuel is in the combustion chamber and contaminates engine oil, so that engine oil is low viscosity.

6. Observation of Field.

1764 (2021) 012172 doi:10.10

doi:10.1088/1742-6596/1764/1/012172

Based on the cylinder head inspection it was found that the diesel fluid was in the combustion chamber, which is explained in figure 2.



Figure 2. Solar is in the combustion chamber.

The formation of a groove injector seal holder in the cylinder head resulting in leakage of fuel into the combustion chamber and diesel fuel flowing from the cylinder head to the oil pan.



Figure 3. The formation of the groove on the cylinder head in the injector seal holder.

7. Result Analysis.

Fuel dilution will affect the engine lubrication system and its fatality results in the hydraulic lock and wear on the liner wall.

Lubricant performance:

- Viscosity decrease.
- Positive fuel on Set-a-flash (4% maximum)
- Fe (cylinder liner, crankshaft, camshaft, pushrods).
- PB & Sn (bearing overlay).
- Cr & Mo (piston rings).
- Cu, Pb, & Sn (bronze bushings).

1764 (2021) 012172 doi:10.1088/1742-6596/1764/1/012172

Increased wear element Cu is found in bearing material, bushings, friction in engine components that come in contact with metal components with metals, causing wear on bearing or bushing elements. As for engine lubricant that is contaminated with diesel fuel causes thinning of the oil film, according to the data in figure 4, where on March 4 and March 30 2016 oil viscosity was recorded at 0.311 and 0.644, the condition of the lubricant being low viscosity. The rate of wear from January to November 2016, wear element Fe, Cu trending is quite high starting from January and followed by a decrease in viscosity from January to March 2016. After March 2016 has been done to repair damaged components so that the lubricant viscosity becomes stable.




Figure 4. Graph of scheduled oil sampling test results (Fe, Cu, and Viscosity)

In the explanation of figure 5 the increase in Fe is balanced by the addition of lubricant at each lubricant change interval at 500 hours [9], enough to increase and including the addition of oil up to 260 liters on January 9, 2016, and 280 liters on June 04, 2016. With the Fe trend, increasing wear occurs in the liner wall. The impact on shiny on the inner liner wall described in Figure 6 [10] [11], lubricant also burns during the process of movement of the piston from BDC to TDC and the combustion process in the [12] combustion chamber occurs [13] and causes the lubricant to decrease, this will result in engine components will be damaged quickly, including bearings, shafts [14].

1764 (2021) 012172 doi:10.1088/1742-6596/1764/1/012172




Figure 5. Graph of scheduled oil sampling testing (Fe vs Add Oil Lubricant).

Figure 6 explains the occurrence of shiny in the liner where there is friction between the piston ring and the liner wall in the shiny region of the surface of the liner caused by scale deposits [15] on the middle and bottom sides. Indications that occurred in oil testing indicated an increase in the Fe element.



Figure 6. Shiny at liner [9].

8. Conclusion.

Engine lubricant mixed with diesel fuel results in reduced lubricant viscosity (fuel dilution) caused by damage to the hardened injector seal, with hardening of the injector seal friction, which occurs with the seal holder and shaped groove. When the unit is operating, the fuel will flow into the combustion

1764 (2021) 012172 doi:10.1088/1742-6596/1764/1/012172

chamber, causing abnormalities in the combustion process and when the unit is not operating, diesel will flow into the combustion chamber and then flow the oil pan. This is affected by the high fuel temperature, damaging the injector seal holder in the cylinder head and not fitting the holder. Groove on the cylinder head wall a maximum of 2 millimeters in-depth, if it exceeds 2 milli it will cause fatality to other engine components. To prevent fuel dilution from occurring, care must be taken regarding the temperature of the fuel. treatment, preventing fuel temperatures from rising beyond 60 °C (150 °F). Preventing back pressure fuel return exceeds the maximum limit of 27 kPa (kilopascal) and performs maintenance by procedures, as well as routine engine lubricant testing, to find out the diesel content of the engine lubricant.

References

- [1] R. De Robbio, M. C. Cameretti, and R. Tuccillo, "Ignition and combustion modelling in a dual fuel diesel engine," *Propuls. Power Res.*, no. xxx, 2020.
- [2] R. Shrivastava and A. Singh, "Research on Failure mode and effect analysis of Diesel Engine," *Int. Res. J. Eng. Technol.*, vol. 5, no. 5, pp. 3516–3521, 2018.
- [3] I. Guide, "Lubrication systems."
- [4] H. Krpan, I. Matanović, and D. Ljubas, "Influence of engine oils dilution by fuels on their viscosity, flash point and fire point," *Nafta*, vol. 61, no. 2, pp. 73–79, 2010.
- [5] K. S. Werner, E. P. Graven, and T. A. Berkman, "Oil and Oil and," vol. 10, no. 5, pp. 948–958, 1991.
- [6] T. Osipowicz, "Reduction of the Common Rail fuel injectors repair costs Reduction of the Common Rail fuel injectors repair costs," no. January, 2017.
- [7] W. Wilarso, T. Wibowo, B. Teguh, and M. Mujiarto, "Analysis of injector spring damage to determine maintenance management diesel engine at PLTD Ampenan," *J. Phys. Conf. Ser.*, vol. 1402, no. 7, 2019.
- [8] M. Services, "Understanding S · O · S Services Tests S · O · S Wear Rate Analysis."
- [9] T. M. S. Motorservice, "Oil consumption and oil loss," 2014.
- [10] O. A. Elhabib and W. Y. Ali, "Inspecting Metallic Wear Particles Contaminating Lubricating Automotive Engine Oils," vol. 2, no. 3, 2013.
- [11] S. Howell-Smith, H. Rahnejat, P. D. King, and D. Dowson, "Reducing in-cylinder parasitic losses through surface modification and coating," *Proc. Inst. Mech. Eng. Part D J. Automob. Eng.*, vol. 228, no. 4, pp. 391–402, 2014.
- [12] S. A. Siddique, K. Vijaya, and K. Reddy, "Experimental Validation and Combustion Chamber Geometry Optimization of Diesel Engine By Using Diesel –Rk," *Int. J. Mech. Eng. Technol.*, vol. 6, no. 2, pp. 976–6340, 2015.
- [13] J. Agboola, B. T. Lebele-alawa, and B. Nkoi, "A Study Of Combustion Temperature Distribution In The Cylinder Of Compression Ignition Engine," no. 11, pp. 304–312, 2018.
- [14] A. Almutairi, D. Wu, B. Guo, A. P. Roskilly, and C. Ottley, "Characterization of Lubricant Degeneration and Component Deterioration on Diesel Engine Fueling with Straight Plant Oil," *Energy Procedia*, vol. 105, pp. 636–641, 2017.
- [15] I. Celik and O. Aydin, "Effects of B100 biodiesel on injector and pump piston," *Tribol. Trans.*, vol. 54, no. 3, pp. 424–431, 2011.

Acknowledgment

Thank you to all of PT. ABCD is engaged in power generation rentals and PT. X, lubricating laboratory test colleagues.